





# Front Fog Lamp Package Installation

## [Installation Instructions Part Number](#)




95262418






TORX T-20





1





2







5







6



7



8



Note: See PI0910B: Accessory Fog Lamp Inoperative. Vehicles built after March 25, 2013 will not require the BCM to be re-programmed.

