



- 1** PLATFORM ASSEMBLY -
TRAILER WEIGHT DISTRIBUTION HITCH
- 2** BOLT / SCREW
- 3** NUT
- 4** PLATE ASM - TRLR WT DISTR

ASSEMBLY PROCEDURE

- A. PLACE HITCH TO FRAME.
- B. LOOSE ASSEMBLE HITCH TO FRAME WITH (2) BOLTS AND NUTS LH AND RH.
- C. LOOSE ASSEMBLE HITCH TO FRAME WITH (1) PLATE AND (2) NUTS LH AND RH.
- D. SECURE HITCH TO FRAME WITH (4) NUTS.

1 85.0 +/- 10.0 Nm